



TECHNICAL BUILD DETAIL 996.1.5

Vehicles Impacted: Porsche 996 Carrera 2 & Carrera 4

Differential spider gears with surface defects like those shown below have the potential to lead to severe transmission damage and even loss of vehicle control. As the spider gear continues to degrade small chunks of hardened metal will be introduced to the rest of the transmission. These chunks will result in damage to other components. If one of these chunks were to get stuck between the gear teeth the differential could lock resulting in a rear axle skid. Gbox carefully inspects differential spider gears and other differential components during disassembly and cleaning to make sure these are in top condition.

